


NARRATIVE

The purpose of this survey is to locate the lot corners and provide a certified survey showing the recently constructed entrance gate posts and new wood deck. Each of the four lot corners were found with a rusty metal fence post marking the lot corners. The Southeast corner had a rebar and cap at the post and the Northwest corner had a naked rebar. A rebar and yellow cap (PLS 4614) was set at the two remaining corners. There was an existing silver metal tag on the NE corner marked LOTS 350, 352 and 357. Basis of bearing, N.89°50'03"E. is the South line of Lot 352 according to the Currant Creek, Sections 35 & 36 subdivision plat prepared by Aspen Engineering and dated May, 1976.

LEGAL DESCRIPTION (Auditor's Tax Deed)

SEC 35 T3S R9W; USM (Utah Special Meridian), S2NE4NW4; N2SE4NE4NW4; (LOT 352 MT VIEW ESTATES).

NOVEMBER 23, 2005



LEGEND

* Property corner-set 5/8" rebar 7 places

| | | | | | | |
|--|-------|------------------------|--|-------|----------|--------|
| SURVEY FOR | | SECTION | TOWNSHIP | RANGE | DATE | SCALE |
| Rose Jansen 7067 So. Woodgreen Rd. West Jordan, Utah 84084 | | NW 1/4 35 | 3 SD. | 9W | 11-23-05 | 1"=80' |
| | | UNTAH SPECIAL MERIDIAN | | | | |
| LOT | BLOCK | PLAT | SURVEY | | | |
| 352 | | | CURRANT CREEK SUBDIVISION Sec. 35 & 36 | | | |

CONTRACT SURVEYORS
REGISTERED LAND SURVEYORS

9740 SO. SITZMARK DR. SANDY, UTAH 84092

Co. Surveyors File # 1608