

Z A-13 0

USDA-FOREST SERVICE

Index

File No. A-13

CORNER RECORD

Tract or

Cor.

Survey No. SECTION 3 No. NW

T. 1 NORTH R. 5 WEST

R.D. ROOSEVELT

County DUCHESNE


Merid. UINTAH SPECIAL

N.F. ASHLEY

State UTAH

CORNER DIAGRAM

N



DESCRIBE CORNER MONUMENT FOUND

FOUND THE STONE, WELL-SET AND MARKED AS DESCRIBED IN THE OFFICIAL RECORDS. ALONGSIDE IS A 2-1/2" GALVANIZED PIPE AND CAP, SET BY PERSONS UNKNOWN TO ME AND STAMPED AS SHOWN BELOW.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

THE SW BEARING TREE DESCRIBED IN THE GLO RECORDS IS ALIVE AND WELL-MARKED. FOUND NO TRACE OF THE SE BEARING TREE.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date


DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

THE CORNER IS ON A GENTLE EAST SLOPE IN AN OPEN STAND OF PONDEROSA PINES, ABOUT 5 FT. SOUTH OF AN E-W FENCE.

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

THE GALVANIZED PIPE DESCRIBED ABOVE WAS STAMPED:



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

POSTED YELLOW SIGNS ON NEARBY TREES.

Work Done By: R. GARY MCCORMICK Title: SURVEY TECH. Date: 8/28/91

REMARKS

CORNER CERTIFIED CORRECT.



Index File No. A-13

T. 1 N. R. 5 W. M. USM

Tract or Surv. No. SECTION 3

Cor. NW