


B*-17

USDA-FOREST SERVICE

Index _____ CORNER RECORD Tract or _____ Cor. _____
 File No. Y-17 Survey No. SECTION 34,35 No. S 1/16
 T. 2 NORTH R. 5 WEST R.D. ROOSEVELT County DUCHESNE
 Merid. UINTAH SPECIAL N.F. ASHLEY State UTAH

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

THERE IS NO CORNER OF RECORD. THIS IS A NEW SECTION SUBDIVISION MONUMENT SET FOR THIS SURVEY.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE OF RECORD.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____
 State _____ Zone _____
 X _____
 Y _____
 Etab. By _____
 Agency _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER


CORNER IS IN RIVER BOTTOM BIRCHES, IN NORTH END OF MEADOW, ABOUT 300 FT. WESTERLY FROM A DIRT ROAD.

| Signature | Title | Division | Headquarters | Date |
|-----------|-------|----------|--------------|------|
| | | | | |

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 1-1/4" x 30" ALUMINUM PIPE, 23" DEEP WITH A 3-1/4" ALUMINUM CAP WITH THE FOREST SERVICE "LOGO" STAMPED:



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

SET ALUMINUM POST WITH USFS DECALS 2 FT. SW OF CORNER.

Work Done By: J. RUSSELL MANNING Title: LAND SURVEYOR Date: 7/22/92

REMARKS

CORNER CERTIFIED CORRECT.

