

CW-14

USDA-FOREST SERVICE

Index

CORNER RECORD

Tract or

Cor.

File No. X-16

Survey No. SECTION 34 No. CE 1/16

T. 2 NORTH R. 5 WEST

R.D. ROOSEVELT

County DUCHESNE

Merid. UINTAH SPECIAL

N.F. ASHLEY

State UTAH

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



THERE IS NO CORNER OF RECORD. THIS IS A NEW SECTION SUBDIVISION MONUMENT SET FOR THIS SURVEY.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE OF RECORD.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature \_\_\_\_\_

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

Signature

Title

Division

Headquarters

Date


DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LIES IN A SWAMPY AREA IN WILLOWS AND GRASS ABOUT 200 FT. WEST OF ROAD TO FISHER CABIN.

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 1-1/4" x 30" ALUMINUM PIPE, 26" DEEP WITH A 3-1/4" ALUMINUM CAP WITH THE FOREST SERVICE "LOGO" STAMPED:



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BUILT STONE COLLAR AROUND CAP. SET AN ALUMINUM POST WITH USFS DECALS 2 FT. SW.

A REBAR WITH STEEL FENCE POST BEARS 320 DEGREES AZ. 3.05 FT.

Work Done By: C. KENT MILLER

Title: LAND SURVEYOR

Date: 7/22/92

REMARKS

CORNER CERTIFIED CORRECT.



Index File No. X-16

T. 2 N. R. 5 W. M. USM

Tract or Surv. No. SECTION 34

Cor. CE 1/16