


ZA 19

USDA-FOREST SERVICE

Index \_\_\_\_\_ CORNER RECORD \_\_\_\_\_ Tract or \_\_\_\_\_ Cor. \_\_\_\_\_  
 File No. A-19 Survey No. \_\_\_\_\_ No. 1/4  
 T 6 S R 6 W R.D. Duchesne County Duchesne  
 M 1. Uintah Special N.F. Ashley State Utah

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Corner position falls on steep west bank of a side drainage to Cottonwood Canyon, found no evidence of original stone.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Found two original bearing trees:  
 A 12" DBH Pinon Pine bears N30° E, 2.6' distant, scribed: "1/4 S35 BT".  
 A 8" DBH Pinon Pine bears S10° E, 181.5' distant, scribing overgrown.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
 Signature \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER


Corner lies on steep west bank of a side drainage to Cottonwood Canyon in scattered Pinon Pine timber. Side drainage drains north from corner position.

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Etab. By \_\_\_\_\_  
 Agency \_\_\_\_\_

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Determined true corner position from found original bearing trees. Position falls on steep, rocky, slope 10' above drainage bottom, impractical to monument. Set two reference monuments: RM 1 is a 30" long, 1" dia., aluminum drive post driven 22" in the ground surrounded by a collar of stone with a 3 1/4" dia. aluminum cap with FS logo stamped:  
 RM1 bears S56° W, 44.37' distant from true corner position. (SEE RM2 INFO. BELOW)



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Scribed a new bearing tree: A 8" DBH Pinon Pine bears S5° 30' E, 43.4' distant from true corner position, scribed: "T6S R6W 1/4 S2" @ DBH, "BT" @ stump.

Nailed a FS Attention sign to a Pinon pine tree 50' southeast of true corner position.


Nailed FS Bearing Tree signs to BT's.

Work Done By: Henry J. Peterson Title: Surveying Tech. Date: May 20, 1991

CORNER CERTIFIED CORRECT

REMARKS:

RM2 is a 30" long, 1" dia., aluminum drive post driven 23" in the ground in a collar of stone with a 3 1/4" dia. aluminum cap with FS logo stamped:  
 RM2 bears N17° 30' W, 29.25' distant from true corner position.



x File No. A-19 T. 6 S. R. 6 W. M. U.S.M. Tract or Surv. No.-Cor. 1/4

SEND 13 Mar 03